

# KOPENHAGA – ДАВ / ОАК / ДУБ – G<sup>1</sup> JESION / ASH / ЯСЕНЬ – G<sup>2</sup>

ZAKRES WYMIAROWY / MEASUREMENTS / РАЗМЕРНЫЙ РЯД:


**H** – wysokość / height / высота, **B** – szerokość / width / ширина



## DP – G

H min. – max. = 283–1284  
B min. – max. = 296–596


WYJĄTKI / EXCEPTIONS / ИСКЛЮЧЕНИЕ  
H min. – max. = 283–570  
B = 796, 896, 996, 1196



## DR – G

H min. – max. = 283–1102  
B min. – max. = 296–596

WYJĄTKI / EXCEPTIONS / ИСКЛЮЧЕНИЕ  
H min. – max. = 283–570  
B = 796, 896, 996, 1196



## DK – G

H min. – max. = 283–1000  
B min. – max. = 296–596

WYJĄTKI / EXCEPTIONS / ИСКЛЮЧЕНИЕ  
H min. – max. = 283–570  
B = 796, 896, 996, 1196



## CZ – AL

Z FREZEM ZEWN. / OUTER MouldING / С ФРЕЗЕРОВОЙ ПО КРАЮ

H min. – max. = 110–282  
B min. – max. = 296–596

OPCJE:  
B = 796, 896, 996, 1196  
OPCJE:  
HxB = 140x146



## CZ – AP

Z WYCIECIEM NA PALEC / WITH FINGER PULL / С ВЫРЕЗОМ ПОД ПАЛЕЦ

H = 140 (const.)  
B = 146 (const.)



## BL – AB

PLASKA / FLAT / ПЛОСКАЯ


H min. – max. = 350–1284  
B min. – max. = 30–295



## BL – BT

Z FREZEM ZEWN. / OUTER MouldING / С ФРЕЗЕРОВОЙ ПО КРАЮ

H min. – max. = 350–1284  
B min. – max. = 50–295



## LN – C

H = 570, 713, 860, 920, 1000  
B = 45x45